

Please refer to

3

and mention the premises when communicating regarding this notice



STATE OF NEW YORK  
DEPARTMENT OF LABOR  
DIVISION OF INDUSTRIAL  
SAFETY SERVICE  
BUREAU OF BOILERS  
488 BROADWAY  
ROOM 309  
ALBANY, N. Y.

8-26-54

NYS Dept. Education  
412 Washington Ave.  
Albany, NY

The inspection report dated 8-18-54; covering steam boiler State No. 22303 & 22304  
situated at State Teachers College  
shows the following changes and repairs are necessary to comply with the provisions of the New York  
State Boiler Code:

Order applies to both boilers

- 1.- You are directed to repair the brickwork around the front head. Rule 14-7.1.

FRB  
Copy-Albany office  
Arch. #

RECEIVED

AUG 30 1954

STATE DEPT. OF  
ARCHITECT

RECEIVED  
AUG 31 1954  
INDUSTRIAL

You are hereby allowed fifteen days in which to make these repairs and changes. If they are not completed within the time allowed, it will be necessary to order the use of the boiler discontinued.

Please address communications to  
DIVISION OF INDUSTRIAL SAFETY SERVICE  
Bureau of Boilers, Room 309  
488 Broadway, Albany, N. Y.

*Edmund J. ...*  
Industrial Commissioner.

DO NO WELDING BEFORE CONSULTING THIS OFFICE

STATE OF NEW YORK



DEPARTMENT OF LABOR

OCT 9 1953

Boiler State No. 22303

Certificate

No.

2867

Chap. 50, Sec. 204, Laws of 1921, requires that the boiler number shall be securely bolted upon each boiler, with metal figures not less than two inches in height, on a metal plate.

DIVISION OF INDUSTRIAL SAFETY SERVICE BUREAU OF BOILERS

Under the provisions of Sec. 204 as amended by Chap. 50, Laws of 1921, you are required to pay the sum of Five Dollars for the inspection and testing of each Boiler mentioned in the Certificate.

Certificate of Inspection of Steam Boilers

This is to Certify that the herein-described steam-boiler

inspected by L. Stannard on 8-12-53 may be

operated at a Pressure not to exceed 60 pounds per square inch. Safety valve set at 60 pounds.

Name N.Y.S. Dept. of Education

Address 412 Washington Ave., Albany, N. Y.

Location of Boiler Teachers College

Type of Boiler H. R. T. (No. and Street) (City) (County) (State) Year Built 1928

Made by Ames I. Works Std. and Std. No. NB 2430

Certificate expires 8-12-54

L. Stannard Supervising Boiler Inspector

Arthur O. Farrell Industrial Commissioner Director Division of Industrial Safety Service

Post this Certificate in a conspicuous place under glass in the Boiler Room or in metal container to be fastened to machine or kept in tool box if boiler is of portable type.

Please refer to

and mention the premises when communicating regarding this notice



STATE OF NEW YORK  
DEPARTMENT OF LABOR  
DIVISION OF INDUSTRIAL  
SAFETY SERVICE  
BUREAU OF BOILERS  
488 BROADWAY  
ROOM 309  
ALBANY, N. Y.

8-14-53

AUG 18 1953

STATE UNIVERSITY  
ARCHITECT

NYS Dept. Education  
412 Washington Ave.  
Albany, NY

8-12-53

22303

The inspection report dated.....; covering steam boiler State No.....  
situated at.....  
shows the following changes and repairs are necessary to comply with the provisions of the New York State Boiler Code:

- 1.- You are directed to cover the front head seam with refractory as discussed at the time of inspection. Rule 14-7.1.

FRB

Copy-Albany office  
Arch. \*

RECEIVED

DO NO WELDING BEFORE CONSULTING THIS OFFICE

You are hereby allowed fifteen days in which to make these repairs and changes. If they are not completed within the time allowed, it will be necessary to order the use of the boiler discontinued.

Please address communications to  
DIVISION OF INDUSTRIAL SAFETY SERVICE  
Bureau of Boilers, Room 309  
488 Broadway, Albany, N. Y.

*Francis J. ...*  
Industrial Commissioner.

Please refer to

and mention the premises when communicating regarding this notice



STATE OF NEW YORK  
DEPARTMENT OF LABOR  
DIVISION OF INDUSTRIAL  
SAFETY SERVICE  
BUREAU OF BOILERS  
488 BROADWAY  
ROOM 309  
ALBANY, N. Y.  
8-14-53

NYS Dept. Education  
412 Washington Ave.  
Albany, NY

AUG 18 1953  
STATE UNIVERSITY  
ARCHITECT


DO NO WELDING BEFORE CONSULTING THIS OFFICE

The inspection report dated 8-12-53 covering steam boiler State No. 22304  
situated at State Teachers College  
shows the following changes and repairs are necessary to comply with the provisions of the New York  
State Boiler Code:

Boiler was found to be in satisfactory condition and may be continued  
in operation at pressure of 60 lbs.

FRB

Copy-Albany office



You are hereby allowed fifteen days in which to make these repairs and changes. If they are not completed within the time allowed, it will be necessary to order the use of the boiler discontinued.

Industrial Commissioner.

Please address communications to  
DIVISION OF INDUSTRIAL SAFETY SERVICE  
Bureau of Boilers, Room 309  
488 Broadway, Albany, N. Y.

STATE UNIVERSITY OF NEW YORK

ALBANY 1, NEW YORK

September 5, 1952

Mr. C. J. White  
State Architect                      Attention: Mr. A. Moses  
State Office Building  
Albany, New York

Subject: Request for Heating Plant Data  
All Units of State University

Reference (a) - Letter from State Architect  
to University dated July 31,  
1952.

Enclosure (A) - Completed Log Form submitted  
without letter by College for  
Teachers at Albany and received  
Sept. 5, 1952.

Dear Mr. Moses:

Enclosure (A) is forwarded in accordance  
with your request in reference (a).

Very truly yours,

OJT:VG  
encl. /  
cc: ✓ Dr. Collins, Albany


Otto J. Teegen  
State University Architect

STATE UNIVERSITY OF NEW YORK

ALBANY 1

OFFICE OF THE UNIVERSITY ARCHITECT

August 18, 1952



Dr. Evan R. Collins  
State University Teachers College  
Albany, New York

Subject: Request for Heating Plant Data  
College for Teachers at Albany

Enclosure (A) - Two (2) copies of Log Form 20-294.46.

Dear Dr. Collins:

We have been requested by Public Works to have your maintenance engineer fill out Enclosure (A) as completely as possible with the data available to him. Please return one form to this office and keep the other for your records.

If you have more than one boiler unit, we will be pleased, upon your request, to send you additional copies of the Log Form.

Very truly yours,

Otto J. Teegen  
State University Architect

OJT:VG

encl.

*E. C. B.*

STATE UNIVERSITY OF NEW YORK

ALBANY 1, NEW YORK

August 18, 1952

Dr. Evan R. Collins  
State University Teachers College  
Albany, New York

Subject: Request for Heating Plant Data  
College for Teachers at Albany

Enclosure (A) - Two (2) copies of Log Form 20-294.46.

Dear Dr. Collins:

We have been requested by Public Works to have your maintenance engineer fill out Enclosure (A) as completely as possible with the data available to him. Please return one form to this office and keep the other for your records.

If you have more than one boiler unit, we will be pleased, upon your request, to send you additional copies of the Log Form.

Very truly yours,

OJT:VG

Otto J. Teegen  
State University Architect

encl.

STATE UNIVERSITY OF NEW YORK

ALBANY 1, NEW YORK

August 27, 1952

MEMORANDUM FOR Presidents of State University Teachers  
Colleges

FROM Hermann Cooper, Executive Dean for  
Teacher Education

Will you please see that a proper distribution is  
made of the attached memorandums to those faculty members  
who will attend the Buffalo workshop.

incs.

*all the copies  
sent to Dr. Cooper*

RECEIVED  
AUG 29 1952  
RECEIVED



STATE UNIVERSITY OF NEW YORK  
ALBANY 1

August 27, 1952

MEMORANDUM FOR Faculties of State University Teachers Colleges  
attending Buffalo Workshop

FROM Hermann Cooper, Executive Dean for Teacher  
Education

SUBJECT Buffalo Workshop

Opening session - Dinner, Wednesday, September 3  
Closing session - Luncheon, Tuesday, September 9

Board and Room - Rate for board and room is \$55. Each faculty member is to pay board and room charge at time of registration. This office will reimburse faculty members by regular State procedure when duly receipted bill is presented with expense account.

Railroad travel - Faculty members traveling by railroad will be reimbursed for tax exempt railroad fares only. Tax exempt certificate should be secured from the business office of the college before purchasing tickets. Overnight pullman travel will be reimbursed on presentation of pullman stubs with expense account. Pullman stubs must be attached to expense account in order to justify first class railroad fare and pullman accommodations.


Auto travel - A faculty member using personal car to transport other faculty members to conference will be reimbursed at the rate of eight cents per mile provided car is covered by insurance in the name of the State of New York. Faculty members traveling alone in personal cars will be reimbursed on the basis of railroad travel. Whether a faculty member is driving his own car or riding in the car of another, the time of departure and arrival must be indicated on the expense account. Those driving cars and carrying other faculty members must give the names of riders in their cars and those faculty members being transported must indicate with whom they rode. In order to keep costs at a minimum it is suggested that where possible the faculty group from each college travel in one car.

Please refer to

7-3-51

and mention the premises when communicating regarding this notice

NYS Dept. of Education  
NYS College for Teachers  
A. C. Baker Bldg. 2nd Fl.  
Western Ave.  
Albany, N. Y.



STATE OF NEW YORK  
DEPARTMENT OF LABOR  
DIVISION OF INDUSTRIAL  
SAFETY SERVICE  
BUREAU OF BOILERS  
488 BROADWAY  
ROOM 309  
ALBANY, N. Y.

DO NO WELDING BEFORE CONSULTING THIS OFFICE

The inspection report dated 6-29-51; covering steam boiler State No. 22303-22304,  
situated at Albany  
shows the following changes and repairs are necessary to comply with the provisions of the New York  
State Boiler Code:

**Boilers found to be in satisfactory condition and may be  
continued in operation at pressure of 60 lbs.**

Copy-Albany Office

ARD

RECEIVED  
JUL 10 1951  
STATE UNIVERSITY  
ARCHITECT

You are hereby allowed fifteen days in which to make these repairs and changes. If they are not completed within the time allowed, it will be necessary to order the use of the boiler discontinued.

Please address communications to  
DIVISION OF INDUSTRIAL SAFETY SERVICE  
Bureau of Boilers, Room 309  
488 Broadway, Albany, N. Y.

*Industrial Commissioner*

3  
Please refer to

Mr. Zeegan  
6-13-51  
and mention the premises when communicating regarding this notice

His Dept. of Education  
E. G. Baker, Prin. etc. etc.  
Western Ave.  
Albany 3, N. Y.



STATE OF NEW YORK  
DEPARTMENT OF LABOR  
DIVISION OF INDUSTRIAL  
SAFETY SERVICE  
BUREAU OF BOILERS  
488 BROADWAY  
ROOM 309  
ALBANY, N. Y.

DO NO WELDING BEFORE CONSULTING THIS OFFICE

The inspection report dated 6-13-51 ; covering steam boiler State No. 540  
situated at Albany,  
shows the following changes and repairs are necessary to comply with the provisions of the New York State Boiler Code:

1. Because of general deterioration in the form of internal pitting, internal and external corrosion of the shell and front head this boiler must be permanently discontinued from service, and stamped **CONDEMNED** as per Rule 14-2.15. These conditions were called to the owners attention 10 years ago under date of June 23, 1941.

NEW YORK STATE	
DEPARTMENT	
ED	
JUN 18 1951	
SCHOOL BUILDINGS AND GROUNDS DIVISION	

Copy-Albany Office  
ARM

RECEIVED  
JUN 19 1951  
STATE UNIVERSITY  
ARCHITECT

You are hereby allowed fifteen days in which to make these repairs and changes. If they are not completed within the time allowed, it will be necessary to order the use of the boiler discontinued.

Please address communications to  
DIVISION OF INDUSTRIAL SAFETY SERVICE  
Bureau of Boilers, Room 309  
488 Broadway, Albany, N. Y.

*[Signature]*  
Industrial Commissioner.

3  
Please refer to

6-15-51  
and mention the premises when communicating regarding this notice

NYS Dept. of Education  
E. C. Baker, Prin. Sta. Eng/  
Western Ave.  
Albany 3, N. Y.



STATE OF NEW YORK  
DEPARTMENT OF LABOR  
DIVISION OF INDUSTRIAL  
SAFETY SERVICE  
BUREAU OF BOILERS  
488 BROADWAY  
ROOM 309  
ALBANY, N. Y.

540

DO NO WELDING BEFORE CONSULTING THIS OFFICE

The inspection report dated 6-12-51 ; covering steam boiler State No. 5407  
situated at Albany,  
shows the following changes and repairs are necessary to comply with the provisions of the New York  
State Boiler Code:

1.- Because of general deterioration in the form of internal pitting, internal and external corrosion of the shell and front head this boiler must be permanently discontinued from service, and stamped CONDEMNED as per Rule 14-2.15. These conditions were called to the owners attention 10 years ago under date of June 23, 1941.

Copy-Albany Office

ARM

You are hereby allowed fifteen days in which to make these repairs and changes. If they are not completed within the time allowed, it will be necessary to order the use of the boiler discontinued.

Please address communications to  
DIVISION OF INDUSTRIAL SAFETY SERVICE  
Bureau of Boilers, Room 309  
488 Broadway, Albany, N. Y.

  
Industrial Commissioner.

July 13, 1950

Please refer to

and mention the premises when communicating regarding this notice

State of New York  
State College for Teachers  
Western Avenue  
Albany, N. Y.



STATE OF NEW YORK  
DEPARTMENT OF LABOR  
DIVISION OF INDUSTRIAL  
SAFETY SERVICE  
BUREAU OF BOILERS  
488 BROADWAY  
ROOM 309  
ALBANY, N. Y.

DO NO WELDING BEFORE CONSULTING THIS OFFICE

The inspection report dated July 10, 1950; covering steam boiler State No. 540 & 5407, situated at 612 Washington Ave., Albany shows the following changes and repairs are necessary to comply with the provisions of the New York State Boiler Code:

Because of the age and general deterioration of these boilers they must be discontinued for service after July 1, 1951 as per orders issued June 24, 1948 and June 23, 1941.

RECEIVED

JUL 13 1950

STATE UNIVERSITY  
ARCHITECT

cc- State University

You are hereby allowed fifteen days in which to make these repairs and changes. If they are not completed within the time allowed, it will be necessary to order the use of the boiler discontinued.

Please address communications to  
DIVISION OF INDUSTRIAL SAFETY SERVICE  
Bureau of Boilers, Room 309  
488 Broadway, Albany, N. Y.

Industrial Commissioner.