APPRAISAL BY: H. L. Yoh Company

Div. of Day and Zimmermann, Inc.

CITY & STATE: Newburgh, N. Y.

PROJECT NAME: East Newburgh Urban Renewal Area

PROJECT NO. -- NYR-189 4-6-2-31to33

> 55-63 Broad St. ADDRESS:

> OWNER: Parkhill Harris

### DESCRIPTION OF BUILDINGS

3 story brick, gable roof, apartment house, 22 rooms and 6 @ 3 piece baths, pine floors, plaster walls and ceilings, hot water - oil fired heat.



HISTORY

DATE BUILT: 1880 DATE PURCHASED: 9/15/59

PURCHASE DATA: VOL. 1520 PAGE 280

PURCHASE PRICE: ---

IRS

IMPROVEMENTS SINCE PURCHASE WITH APPROXI-MATE COST AND NECESSARY STRUCTURAL REPAIRS: Unknown - building in need of major repairs

ASSESSMENT: \$ 490.00 Land Buildings 2,950.00

> #31-#33: 123'X100' irreg. LOT: DIMENSIONS and AREA

TOTAL \$3,440.00 ZONING: 2 family residential

TAX RATE: \$91, 13/\$1,000 TOPOGRAPHY: Sloping

\$209.26 TAXES:

NONE SPECIAL ASSESSMENTS:

HIGHEST and BEST USE: "AS IS"

#### VALUATION

(\$14,000.00)FOURTEEN THOUSAND DOLLARS

#### CERTIFICATION

We hereby certify that we have no interest, present or contemplated, in the property and that neither the employment to make the appraisal nor our compensation is contingent on the value of the property. We certify that we have personally inspected the property and that, according to our knowledge and belief, all statements and information in this report are true and correct.

DATE November 15, 1966

Mario Petrelli, SRA

4-6-2-31 to 33

Block

Parcel No.

TYPE Apartments

EXTERIOR - Foundation

Brick and Stone

Walls

Brick

Windows

Wood

Screens

Aluminum

Gutters and Leaders

G.I.

Roof

Gabled

Porches

Enclosed porch

Dormers

Yes

Condition

Poor

INTERIOR - Basement

Ful1

Heat

Hot water - oil fired converted

Hot Water Supply

Winter/Summer hook-up

Plumbing

G. I. and Copper

Wiring

BX

Rooms-- lst Floor

4 rooms and 1 @ 3 piece bath 5 rooms and 1 @ 3 piece bath

2nd Floor

6 rooms and 2 @ 3 piece baths

3rd Floor

7 rooms and 2 @ 3 piece baths

Floors

Pine

Walls

Plaster

Ceilings

Plaster

Kitchen

5 Plain

Bathroom

6 Plain

Closets

Insufficient

Fireplace

None

Condition

Very poor

Outbuildings

Garage - Two car frame poured concrete back,

very poor condition.

RENT

See page 4 for economic rent

4-6-2-31to33

Block

Parcel No.

BUILDING SKETCH :		AREA CALCULATIONS
00000000		LOT 123' X 101' = 12,423 s.f. irreg.
1		
		• • • • • • • • • 21'X70' = 1,470 s.f.) $X = 8,836$ s.f.
000000000		• • • • • • • • • • • • • • • • • • •
0 • 0 0 0 0 0 0		2,184 s.f.
00000000		• 11'X40' = 440 s.f. X 2 = 880 s.f.
0 • 0 0 0 0 0 0	00000000	
139		N
100		
1.1/		
N		
84		
	0000000000000000000	
0	000000000000000000000000000000000000000	0 0000
00000000		
0 0 0 0 0 0 0 0		000000
0000000		• • • • • • •
NT - 4-	to scale	

# COST APPROACH

IAND #31-#33: 123' @ \$50.00/FF =

\$ 6,150.00 land value

### BUILDINGS

2,184 s.f. gr. area \$27.25 unit cost \$59,514.00 5@ 3 pc. baths + 1,000.00 Sprinkler 791.00 \$61,305.00 cost new depr. 90% 55,175.00 depr. value 6,130.00 \$6,130.00 500 s.f. garage depr. value \$73.00 73.00 \$6,203.00

\$ 6,203.00 building value \$12,353.00 property value

VALUE INDICATED BY COST APPROACH \$ 12,350.00

4-6-2-31to33

Block Parcel No.

# SUBJECT PROPERTY INCOME ANALYSIS

## ANNUAL REASONABLE EXPENSE

FIXED CHARGES Taxes, Real Estate \$ Insurance \$ 100.00	\$ 100.00
OPERATING EXPENSES         Management       \$ 259.00         Fuel       \$ 600.00         Electricity       \$ 100.00         Water       \$ 100.00         Repairs       \$ 300.00         Supplies       \$         Miscellaneous       \$         Miscellaneous       \$         Miscellaneous       \$	\$ 1,359.00
TOTAL REASONABLE ANNUAL EXPENSE	\$ 1,459.00
Effective Age 65 Years Remaining Life 10 Years Land Value \$ 6,150.00	
CAPITALIZATION PROCESS - BUILDING RES	DUAL
GROSS ANNUAL FAIR INCOME	
ANNUAL EFFECTIVE GROSS INCOME	
	1,459.00 \$ 2,429.00
Total Annual Fair Expense	1,459.00 \$ 2,429.00
Total Annual Fair Expense	1,459.00 \$ 2,429.00 
Total Annual Fair Expense	1,459.00 \$ 2,429.00 <u>768.00</u> \$ 1,661.00
Total Annual Fair Expense	1,459.00 \$ 2,429.00 <u>768.00</u> \$ 1,661.00

MT MW MW A A A A A A A A A A A A A A A A A		UR 8	UR 82	4-1-3-12
ELEMENTS OF COMPARABILITY:	SUBJECT	COMP. # 1	COMP. #2	COMP. #3
Quality of Location	Fair	Fair	Fair	Fair
Quality of Construction	Avg.	Avg.	Avg.	Avg.
Physical Condition	Fair	Fair	Fair	Fair
No. of Stories	3 & Bsmt.	3	2	
Sq. Ft. Area Excl. Base.	2,624 s.f.	2,395 s.f.	3,252 s.f.	3,544 s.f
Price per Sq. Ft. Gross Bldg. Area		\$5.63	\$3.84	\$4.51
No. of Rooms (Residntl.)	22	16	13	19
Price per Room	None	\$843.00	\$961.00	\$842.00
Facilities: Kitchen	5 Plain	2		4
Bath	6 Plain	2	4	4
Heat Hot	vater/oil	Hot water	Hot water	Hot water
Others 2 car garage 25'X20	Ď'			
Sprinkler System				
	<u>}</u>	•		
Lot Sîze	123'X100'	70'X90'	60'X130'	110'X149'
Income (Actual & Vac. Est.)	\$4,320.00	\$1,800	\$3,360	\$4,800.00
No. Floors or Apts. Occ. at Time of Sale				
Gross Income Multiplier	None	7.5	3.72	3.3
Date of Sale	9/15/59	8/31/62	2/23/62.	5/31/60
Sales Price	Unknown	\$13,500.00	\$12,500.00	\$16,000.00
INDICATED COMPARABLE VALUE (	OF SUBJECT	PROPERTY: S	14.000.00	
CONCLUSIONS & REASON FOR MAI				
Subject superior to Sale #				
Subject superior to Sale #:				
Sale #3 superior to subject	because of	building si	ze.	
It is this appraiser's opin	nion that the	ne subject pr	operty would	d sell
for \$14,000.00.				

		# t	#V	
	4-6-2-31 to 33			
Block	Parcel No.			

### CORRELATION AND FINAL ESTIMATE

In determining fair market value by the cost approach, the Boeckh's Manual of Appraisals was used with the appropriate conversion factor and type of building and construction.

Rentals of many and varied apartments, stores and similar office space were analyzed to determine a valuation under the Income or Capitalization Approach. However, in many instances, the buildings have been so vandalized and are so dilapidated that the income approach or the cost approach would not reflect fair market value. In many instances there have been long periods of vacancy. Consequently, the income approach and the cost approach have been almost totally ignored in arriving at fair market value.

Therefore, the principal factor used in establishing fair market value was the use of the market data approach: What the informed willing buyer and the informed willing seller would agree to consummate a transaction. Intra-family, corporate sales and forced sales, while noted and studied, did not influence the estimate of value placed herein.

Based on the analysis made, it is my opinion that the fair market value of this parcel is:

FOURTEEN THOUSAND DOLLARS (\$14,000.00)

## CORRELATION AND FINAL ESTIMATE


The final estimate of fair market value for the subject property is supported by all three of the approaches.

Weight is given to the market approach as reflecting the market value of the subject property.

4-6-2-31-33

Block Parcel No.

7



Located on the South side of Broad Street 100' East of Grand Street.

Accrued depreciation reflects physical, functional-curable and incurable, and economic obsolescence.

The cap rate on this property reflects the accelerated return a prudent investor would receive from the capital investment, plus a reasonable return. This reflects the high degree of risk involved in this type property.

4-6-2-31-33

A-6-2-31-33

A-6-2-31-33

Parcel No.3/-33